


25. End face drawing




■ Usage

Used for a positioning stopper.

■ Shapes Overview

This forming tool cuts and draws a workpiece.

Example



The higher the drawing height is in the straight face of the end face, the more the workpiece is pulled in.

Request for a quotation is [here](#).