

## 27. Simultaneous drawing of top and bottom



### ■ Usage

Used for fixing electric parts.


### ■ Shapes Overview

The top and bottom of the shape are cut and formed simultaneously at the same time with one punching.

### Examples



The surface of the workpiece.



The back side of the workpiece.

Request for a quotation is [here](#).