


28. Drawing




■ Usage

Used for bottom parts of products.

■ Shapes Overview

A required shape is formed with 1 punching or multiple punchings.

Examples




Obround shape
If the rising part is high, the work piece is easy to be deformed.



Triple drawing.



Drawing of square shape.



The example of processing to the end face of the workpiece.

Request for a quotation is [here](#).