


30. Honeycomb drawing



■ Usage

Even if the material thickness is changed thinly, the material has strength.

Cost reduction of materials and weight saving can be expected.

■ Shapes Overview

A workpiece is processed continuously with the punch cutting edge which is shaped into honeycomb.

Example

Request for a quotation is [here](#).